



These instructions use techniques which may induce mechanical stress on individual parts. Use at your own risk.





## Parts List

### Notes



Instructions are for a single curve track section. Multiply part quantity as required for multiple curves.





1





2




3



4





**1**

1x  
1x

**2**

1x

---

**3**



1x    1x

**x4**

6



7



8

