


L-Gauge




Ballasted R40 Curve Baseplates

Reference Instructions Sheet

005

Rev
A



Parts List


Notes

Instructions are for a quarter circle curve section. Multiply part quantity as required for larger sectors.


Parts shown in red and yellow can be substituted with any other colour.



35x




20x




4x



24x



16x



101x



6x




24x





12x

A




B




mirror images


C





1





2




3




4








1




2




3



4




5




6




5x



7




8




9




7x





10






12








1




2



3



4



5

