





Ballasted R56 Curve Baseplates

Reference Instructions Sheet

010

Rev
A





Parts List

Notes


Instructions are for a quarter circle curve section. Multiply part quantity as required for larger sectors.

Parts shown in red and yellow can be substituted with any other colour.








A





1




2




3





4




5




6




7




8




9





10




11





12





B




1




2




3





4




5





6




C





1




2




3





4





5




6




7




8




9



10



11



12

