





# Ballasted R88 Curve Baseplates

Reference Instructions Sheet

012

Rev  
A





## Parts List

### Notes

Instructions are for a quarter circle curve section. Multiply part quantity as required for larger sectors.


Parts shown in red and yellow can be substituted with any other colour.











A



1





2







3





4



5





6






7





**B**








1




# 2



3





4







5



6





C







1





2





3




4



5




C








1





2




# E



1




2








3




5



6









**F**





1




2



# 3




4







5



6





7

