





# Ballasted R104 Curve Baseplates

Reference Instructions Sheet

013

Rev  
A





## Parts List

### Notes

Instructions are for a quarter circle curve section. Multiply part quantity as required for larger sectors.


Parts shown in red and yellow can be substituted with any other colour.











A



1





2







3





4



5




6






7





**B**









1




2



3




4






5





C







1





2




3



4





D








1




2



3





4







5



6





E







1





2




3



4





**F**









1




# 2



3




4








5



6





# G









1




2



3




4








5



6



7  13x

