





Ballasted R72 Curve Baseplates

Reference Instructions Sheet

011

Rev
A




Parts List

Notes

Instructions are for a quarter circle curve section. Multiply part quantity as required for larger sectors.

Parts shown in red and yellow can be substituted with any other colour.



A


B



C

D

A  **D**
mirror images


A






5x

3x






55x




7x



2x




5




6





7




B




1




2




3




4





5




C




1




2





3





4



5




6




7




4x





4x




D





1





2




3





4



5



6



7

