


Ballasted R104 Curve Baseplates


Reference Instructions Sheet

013

Rev
B



520 pcs





Parts List

Notes



Instructions are for a quarter circle curve section. Multiply part quantity as required for larger sectors.

Parts shown in red and yellow can be substituted with any other colour.









A





B





C





D



E



F



G

