




Ballasted R120 Curve Track




PennLUG
variation



Reference Instructions Sheet

018

Rev
A



These instructions use techniques which may induce mechanical stress on individual parts. Use at your own risk.


Parts List

Notes



Instructions are for a single curve track section. Multiply part quantity as required for multiple curves. 32x required for complete circle.

This ballast method requires Bricktracks R120 curve (P/N R120PFDBG8)



Parts shown in yellow can be substituted with any other colour.





1





2




3




4





5



6



7



8

