


L-Gauge





# Ballasted R120 Curve Baseplates

Reference Instructions Sheet

024

Rev  
A

586 pcs





## Parts List

### Notes



Instructions are for a quarter circle curve section. Multiply part quantity as required for larger sectors.

Parts shown in red and yellow can be substituted with any other colour.






# A




# B







# C




# D



# E





# F





# G



# H

